	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
1	BRS	L1	4191	ignit$3 near3 (capacitor capacitance)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/04/20 20:52	
2	BRS	L2	219	1 same resonan$2	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/04/20 20:27	

	Error Definition	Errors
1		0
2		0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
3	BRS	L3	130	2 same (lamp light)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/04/20 20:27	
4	BRS	L4	99	3 and 315/$.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/04/20 20:28	

	Error Definition	Errors
3		0
4		0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
5	BRS	L11	141404	current same voltage same (sensor sensing measur$3)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/04/20 20:56	
6	BRS	L12	3098	11 same ignit$3	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/04/20 20:56	

	Error Definition	Errors
5		0
6		0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
7	BRS	L13	610	12 same (open short)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/04/20 20:57	
8	BRS	L14	88	13 and 315/$.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/04/20 21:18	

	Error Definition	Errors
7		0
8		0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
9	BRS	L15	318	13 and (stop$3 shut$4 disabl3)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/04/20 20:58	
10	BRS	L16	38	14 and 15	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/04/20 20:58	

	Error Definition	Errors
9		0
10		0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
11	BRS	L17	38	15 and 315/$.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/04/20 21:03	
12	BRS	L20	1	5241242.pn.	USPAT	2003/04/20 21:12	
13	BRS	L21	1	20 and converter	USPAT	2003/04/20 21:12	

	Error Definition	Errors
11		0
12		0
13		0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
14	BRS	L24	19	12 and 315/82.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/04/20 21:21	
15	BRS	L27	75	11 and 315/82.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/04/20 21:21	

	Error Definition	Errors
14		0
15		0